




* Provas i glaslistens spår.



Rev.Nr	Ändring och / eller medd.nr			Datum	Sign.	Godk.																						
<table border="1"> <thead> <tr> <th colspan="2">Generella toleranser</th> </tr> <tr> <th>Mått</th> <th>Tillåten tolerans</th> </tr> </thead> <tbody> <tr> <td>> 0 - 3</td> <td>±0,3</td> </tr> <tr> <td>> 3 - 7,5</td> <td>±0,4</td> </tr> <tr> <td>> 7,5 - 15</td> <td>±0,5</td> </tr> <tr> <td>> 15 - 25</td> <td>±0,8</td> </tr> <tr> <td>> 25 - 40</td> <td>±1,0</td> </tr> <tr> <td>> 40 - 75</td> <td>±1,3</td> </tr> <tr> <td>> 75 - 125</td> <td>±1,6</td> </tr> <tr> <td>> 125 - 200</td> <td>±2,0</td> </tr> <tr> <td>> 200 - ∞</td> <td>±1,5%</td> </tr> </tbody> </table>		Generella toleranser		Mått	Tillåten tolerans	> 0 - 3	±0,3	> 3 - 7,5	±0,4	> 7,5 - 15	±0,5	> 15 - 25	±0,8	> 25 - 40	±1,0	> 40 - 75	±1,3	> 75 - 125	±1,6	> 125 - 200	±2,0	> 200 - ∞	±1,5%	Datum	Skala/Scale	Ritad av/Drawn by	Kund/Customer	 <p>Polybase AB Västanvägen Kronslätt Företagspark 245 42 Staffanstorp</p>
Generella toleranser																												
Mått	Tillåten tolerans																											
> 0 - 3	±0,3																											
> 3 - 7,5	±0,4																											
> 7,5 - 15	±0,5																											
> 15 - 25	±0,8																											
> 25 - 40	±1,0																											
> 40 - 75	±1,3																											
> 75 - 125	±1,6																											
> 125 - 200	±2,0																											
> 200 - ∞	±1,5%																											
	201119	10:1	RS	Polybase AB																								
Area (mm ²)		Ersätter/Replace	Profilnamn/Profilenamn		Ritn.nr/Profil nr	Rev.																						
24/1		Fr0855	TPE tätning																									
Material		Ersatt av/Replaced of	ersätter 3mm kronlist		Kund.ritn.nr.																							
SEBS/PP					4010																							